


Spare parts for EURO20 NG DN150 (standard and reinforced versions)




All types since 2003 DN150	Standard Version		Reinforced Version	
	References anti clockwise	References clockwise	References anti clockwise	References clockwise
Kit seal bush and bush lock (5 sets)	182071 up to end 2010 182072 from 2011	182072	-	182073
Kit tightness of the valve (5 sets)	182196	182196	182196	182196
Kit operating system	182200 up to end 2010 225011 from 2011	182201	-	182201

Warning: from beginning of 2011, for anti-clockwise valves, the screw V24 has been replaced by the screw V26


Help for repair:

Necessary tools: wrench of 62 and 42


Linked products



Spare parts for EURO20 NG
- Bonnet disassembling



Spare parts for EURO20 NG
- Operating system
complete replacement



Spare parts for EURO20 NG
- Gate and body bonnet
gasket replacement



Spare parts for EURO20 NG
- Seal bush with 2 O'rings
and bush lock replacement

The information on this sketch is, to the best of our knowledge correct at the time of printing. However Saint-Gobain are constantly looking at ways of improving their products and services therefore reserve the right to change without prior notice, any of the data shown. Any orders placed will be subject to our Standard Conditions of Sale, available on request.